SUBJECT FIT Task Request

- FROM Martha M. McKee 6AWSE

TO Dave Peters, 6ES-SH

Please task FIT to complete the following work: (preliminary assessment, reconnaissance inspection, enforcement support, etc.)

SITE #	SITE NAME	TYPE OF WORK
OK 1033	StillwaterSLF	redopa ; recon
0 K 1064	Surray Refinery	redopa recon
DK 1309	Stapp apirboral bit	redo paí recon (metals)
OK1486	Texaco Pit	recon
01< 1911	Sun Petro Producto	recon
0K 2747	Transfer Station re	edo pa , re con
OK 2844	Stephens Dunp	pa recon
Details of	Assignment (if necessary):	
0 K 350 V	Terra Nitrogen	pa' recon
ok 3127	Southwest Pickling	(old lagoons)
OK 4031	\ - ~	pa ; secon
OK 4588	sur Pipeline pa	pa ; secon
CONCUR:	M. McKee Section thief 67/83	

cc: McKee, Files

